



Photo 1 – View of damage to the left wing root (Courtesy of FAA)



Photo 2 – View of substantial damage to the composite left wing (Courtesy of FAA)



Photo 3 – View of damage to the trailing edge of the outboard left wing (Courtesy of FAA)



Photo 4 – View of damage to left aileron (Courtesy of FAA)



Photo 5 – View of white paint transfer on the asphalt of Runway 34 (Courtesy of FAA)