

From: [REDACTED]
To: [REDACTED]
Subject: N2844T
Date: Monday, June 19, 2017 2:11:02 PM

Mr. Hicks,

Initial inspection of the brake system found the R/H brakes to be weak (excessive pedal travel). The right brake could be pumped up but would bleed off pressure. Disassembly of the right brake actuator found the piston ring had failed allowing pressure to bleed off preventing proper braking of the aircraft.

If I can help further please let me know.

Thanks

Butch

Butch Johnson

Maintenance Chief

Accountable Manager

U.S. Aviation Group LLC.

[REDACTED]

Denton, Texas 76207

[REDACTED]