



Photo 1 – View of inverted airplane (photo courtesy of the pilot)



Photo 2 – View of damaged left wing lift struts (photo courtesy of the pilot)