



Photo 1 – Damaged Engine Mounts (Photo Courtesy of FAA)



Photo 2 – Buckled Skin Along Fuselage (Photo Courtesy of FAA)