



Photo 1 – View of the first touch down point and asphalt perimeter (Courtesy of FAA)



Photo 2 – View of damage to the left wing strut (Courtesy of FAA)