



Photo 1 – View of damaged right wing lift strut (photo courtesy unknown)



Photo 2 – View of damaged vertical stabilizer and rudder (photo courtesy unknown)