



Engine Cowling

Photo 1 – View of the damage to the engine cowling (Courtesy of Operator)



RH White Blade

Photo 2 – View of damage to the white blade (Courtesy of Operator)



Photo 3 – View of damage to the vertical stabilizer (Courtesy of Operator)