



Photo 1 – Front view of damaged lift strut (Photo courtesy of the FAA)