



Photo 1 – View of damaged right wing lift strut (photo courtesy of pilot)