



Photo 1 – View of damage to rudder (Courtesy of FAA)



Photo 2 – Wreckage path diagram (Courtesy of FAA)