



Photo 1 –View of Right Wing Damage (Photo Courtesy of FAA)



Photo 2 – Marker Buoy in Harbor (Photo Courtesy of FAA)