



Photo 1 – View of damage to tail rotor driveshaft (Courtesy of FAA)



Photo 2 – View of damage to main rotor blade (Courtesy of FAA)