



Photo 1 – Substantially Damaged Main Rotor Blade (Photo Courtesy of FAA)



Photo 2 – Substantially Damaged Tail Boom (Photo Courtesy of FAA)