



Photo 1 – View of landing gear embedded in semi-truck (photo courtesy of FAA)



Photo 2 – View of damaged airplane from front (photo courtesy of the FAA)