



Photo 1 – Substantially Damaged Main Rotor Blade (Photo Courtesy of FAA)