



Photo 1 – View of damage from the side (photo courtesy of the FAA).



Photo 2 - View of broken engine mount (photo courtesy of the FAA)