



Photo 1 – View of damage to the tail rotor drive shaft and the main and tail rotor blades (Courtesy of FAA)