



Photo 1 – View of damage to the vertical and horizontal stabilizer and the tail rotor drive shaft (Courtesy of FAA)