



Photo 1 – View of damage to the tail rotor and vertical stabilizer (Courtesy of FAA)