



Photo 1 – View of damage to the tailboom, the tail rotor drive shaft, and main rotor system (Courtesy of FAA)