



Photo 1 – View of damage to the main rotor system and the tailboom (Courtesy of Operator)