



Photo 1 – Substantially Damaged Fuselage (Photo Courtesy of FAA)



Photo 2 - Substantially Damaged Empennage (Photo Courtesy of FAA)




Photo 3 – Tost and Schweizer Tow Rings from Accident (Photo Courtesy of FAA)