

GAA17CA489

FACTUAL

The pilot reported that, during a go around after a low approach, the left cabin door opened. He added that he reached back to close the door and the airplane aerodynamically stalled. The pilot was unable to recover and the airplane impacted the ground and struck multiple fences.

The airplane sustained substantial damage to the fuselage.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

~~The pilot failed to submit the National Transportation Safety Board NTSB Form 6120.1 Pilot/Operator Aircraft Accident/ Incident Report after multiple requests.~~