



Photo 1 – Substantially Damaged Fuselage, Tail Boom, and Main Rotor (Photo Courtesy of FAA)