



Photo 1 – View of airplane inverted (photo courtesy of the FAA)



Photo 2 – View of damaged empennage and wings (photo courtesy of the FAA)