



Photo 1 – View of empennage damage (photo courtesy of the FAA)



Photo 2 - View of sand bar (photo courtesy of the FAA).