



Photo 1 – View of damaged left wing lift struts and rudder (photo courtesy of the pilot)