



Photo 1 – View of damaged right wing (photo courtesy unknown)



Photo 2 – View of damaged right wing leading edge with taxiway sign (photo courtesy unknown)