



Photo 1 – View of empennage damage (photo courtesy of the FAA)



Photo 2 - View of the three-hook banner release mechanism (photo courtesy of the Operator)