



Photo 1 – View of right wing damage (photo courtesy of the pilot)



Photo 2 - View of broken weld on left main landing gear axle (photo courtesy of the pilot)