



Photo 1 – View of damage to the left wing and right-wing strut (Courtesy of FAA)



Photo 2 – View of the landing gear strut (Courtesy of FAA)



Photo 3 – View of damage to the bolts that were not provided in the manufacturer’s kit (Courtesy of FAA)