



Photo 1 – Overview of Accident Site (Photo Courtesy of Massachusetts Department of Transportation, Aeronautics Division)



Photo 2 - Substantially Damaged Right Wing (Photo Courtesy of FAA)



Photo 3 – Engine Cowl Plug as Found After Accident (Photo Courtesy of FAA)



Cowl plug location after pilot removed it from engine cowl, post-accident.

Photo 4 – Overview of Accident Airplane and Cowl Plug (Photo Courtesy of FAA)