



Photo 1 – View of damage to the upper cabin (Courtesy of Operator)



Photo 2 – View of damage to the tailboom (Courtesy of Operator)