



Photo 1 – View of fuselage damage (photo courtesy of the FAA)



Photo 2 - View of right inboard main landing gear door actuator hose (photo courtesy of the Operator)