



Photo 1 – View of damaged right wing leading edge (photo courtesy of airport maintenance)