



Photo 1 – View of right wing spar damage looking up from right landing gear well (photo courtesy of FAA)