




Photo 1 – View of damaged engine mount (photo courtesy of the FAA)