



Photo 1 – View of the damaged pressure vessel (Photo courtesy of the FAA)



Photo 2 – View of hole in left main landing gear tire (Photo courtesy of the FAA)