



Photo 1 – View of damaged empennage from rear of airplane (Photo courtesy of the FAA)



Photo 2 – View of damaged right wing (Photo courtesy of the FAA)