



Photo 1 – View of airplane after impacting pole (Photo courtesy of the flight school)



Photo 2 – View of damaged right wing (Photo courtesy of the flight school)