



Photo 1 – View of damage to the longerons and spar carry through (Courtesy of FAA)