



Photo 1 – View of damaged left horizontal stabilizer (Photo courtesy unknown)