



**Photo 1 – View of damaged empennage (Photo courtesy unknown)**