



Photo – View of damage to left main landing gear attachment point (Courtesy of FAA)



Photo 2 – View of damage to the left main landing gear strut and wheel (Courtesy of FAA)



Photo 3 – View of the extension casting failure at the landing gear strut attachment points (Courtesy of Operator)