



Photo 1 – View of missing windscreen, windows, and greenhouse (Courtesy of FAA)



Photo 2 – View of retainer windshield top missing through-bolts and greenhouse support (Courtesy of FAA)