



Photo 1 – View of left lower fuselage damage (courtesy of the FAA)



Photo 2 – View of bent tailwheel (courtesy of the FAA)