



Photo 1 – View of damage to the outboard section of the main rotor blade (Courtesy of FAA)




Photo 2 – View of a hole in the top of the main rotor blade (Courtesy of FAA)