



Photo 1 – View of damaged right wing (Photo courtesy of FAA)



Photo 2 – View of damaged tail cone (Photo courtesy of FAA)



Photo 3 – View of damaged rudder (Photo Courtesy of FAA)