



Photo 1 – View of damage to the lower left fuselage stringer (Courtesy of Operator)



Photo 2 – View of damage to the lower right fuselage stringers (Courtesy of Operator)