



Photo 1 – View of damaged vertical stabilizer (Photo courtesy of the Operator)